

RESTORATION OF THE MILLENNIUM GREEN FINGERPOST



Before work started on the post



Finial has been removed



Starting to remove the 1st finger



Removing the 1st finger



First finger off the post



Removal of the broken finger



There should be a gap between the inner post and the collar but it is full of rust



Last finger removed



Gas cutting to remove the remains of the inner post



What was left behind